

25X1D

BEST COPY
Available
THROUGHOUT
FOLDER


A/CFT / Eng - OK
Camera - OK

Stall check at 20m
B/W activated for Gen. out (00:124)

D.C. Voltage Reg. reset up 1.5V.
BW Key, Mod Volt Sensor 1 Volt to high

<u>VI</u>	normal	
9	no activity	
12	"	"
13	brief	"
O.S.	little	"

25X1A




Nav/aids OK

Time Lake Generator

Not reflected in any of the

25X1A




Reports. Only found when
Intell. Analysis is made. Was
regated by [redacted] at Critique.
Is an Action Item for S/m.

25X1A

25X1A

Uld 03/00002-06002



Next 1 Page(s) In Document Exempt